

Modelli coinvolti:

QE50QN90CATXZT	QE85QN900CTXZT	RB50DG602ES9EF	BRB26705FWW/EF
QE65QN90CATXZT	QE55QE1CAUXZT	RB53DG703DS9EF	BRB26703CWW/EF
QE75QN90CATXZT	QE32Q50AEUXZT	RB53DG706BS9EF	BRB30600EWW/EF
QE43QN90CATXZT	QE98Q80CATXZT	RB53DG706CS9EF	BRB26602EWW/EF
QE85QN90CATXZT	QE50LS01BGUXZT	RF65DG960ESREF	BRB26600EWW/EF
QE50Q60CAUXZT	QE43LS01BGUXZT	RF65DG9H0EB1EF	BRB26605EWW/EF
QE85Q60CAUXZT	QE55LS01BGUXZT	RF65DG9H0ESREF	BRB26703EWW/EF
QE43Q60CAUXZT	UE43AU7090UXZT	RS62DG5003S9EF	BRB26600FWW/EF
QE55Q60CAUXZT	UE65AU7090UXZT	RS65DG54M3SLEF	BRD27603FWW/EF
QE65Q60CAUXZT	UE55AU7090UXZT	RH69CG895DS9EF	BRD27703EWW/EF
QE75Q60CAUXZT	UE50AU7090UXZT	RF50C530ES9/EF	WW11BB945DGMS3
QE65QN800CTXZT	QE55Q70DATXZT	RB38T607BS9/EF	WW11BB944DGBS3
QE85QN800CTXZT	QE65Q70DATXZT	RB38C7B6DB1/EF	WW11BB744DGES3
QE75QN800CTXZT	QE75Q70DATXZT	RB33B610EBN/EF	WW11BB744DGWS3
SP-LFF3CLAXXE	QE85Q70DATXZT	RB33B610ESA/EF	WW11BB744DGBS3
QE55S90CATXZT	QE85Q70CATXZT	RB33B610EWW/EF	WW11BGA046TTET
QE77S95CATXZT	UE55CU8570UXZT	RS68CG882EB1EF	WW11DG5B25TEET
QE65S95CATXZT	UE65CU8570UXZT	RS6HA8891SL/EF	WW11DG6B85LHU3
QE55S95CATXZT	UE50CU8570UXZT	RF48A400EB4/EF	WW90DB7U94GBU3
QE75QN85CATXZT	QE43LS05BGUXZT	RF48A400EM9/EF	WW90DB7U94GEU3
QE55QN85CATXZT	QE75LST7TCUXZT	RF50A5202S9/ES	WW11DB7B94GBU3
QE65QN85CATXZT	QE65LST7TCUXZT	RF50C510ES9/EF	WW11DB7B94GEU3
UE65CU7170UXZT	QE55LST7TGUXZT	RS68CG853EB1EF	WW11DB8B95GBU3
UE50CU7170UXZT	QE98QN90AATXZT	RS68A854CSL/EF	RB53DG706AB1EF
UE43CU7170UXZT	SP-LSP7TFAXXE	RH69CG892DS9EF	WW90T534DAWCS3
UE75CU7170UXZT	SP-LSP9TFAXXE	RS67A8810S9/EF	WW90T534DTW/S3
QE55Q80CATXZT	HW-B750D/ZF	RB38A7CGTS9/EF	WW90T754DBT/S3
QE50Q80CATXZT	HW-Q930D/ZF	RL38C776ASR/EF	WW90T734DWH/S3
UE75CU8070UXZT	HW-Q990D/ZF	RB34C775CS9/EF	WW90CGC04DTEET
UE85CU8070UXZT	HW-Q800D/ZF	RB38C7B6AB1/EF	WW90T684DLN/S3
UE43CU8070UXZT	HW-Q700D/ZF	RB38C634DSA/EF	WW90T684DLH/S3
UE55CU8070UXZT	HW-S60B/ZF	RS68A8830S9/EF	WW90T634DLECS3
UE50CU8070UXZT	HW-S50B/ZF	BRB26705DWW/EF	WW90T504DAWCS3
QE75QN900CTXZT	MX-ST50B/ZF	BRB30600FWW/EF	WW90CGC04DTHET
QE65QN900CTXZT	RB50DG601EB1EF	BRB26705EWW/EF	WW80T734DWH/S3

Modelli coinvolti:

WW80CGC04DTEET	NV7B4140VBB/U5	DW60A6092BB/ET	LS27BG650EUXEN
WW80CGC04DTHET	NV7B5760WBK/U5	DW60A6090BB/ET	LS34C652UAUXEN
WD10T534DBW/S3	NV75T9579CD/ET	DW60A6080BB/ET	LS27A800NMPXEN
WD90T534DBW/S3	NV75T8979RK/ET	DW60A8050BB/ET	LS24A600UCUXEN
DV90BB7445GBS3	NV7B4540VBB/U5	DW60M6050BB/EG	LS49CG950SUXEN
DV90BB7445GES3	NV7B44403BS/U5	DW60A6090IB/ET	LS32BG750NPXEN
DV90BB5245AES3	NV7B4340UBS/U5	DW60A6092IB/ET	LS25BG400EUXEN
DV80T5220TT/S3	NV7B4540VBS/U5	DW50R4040BB/EO	LS27BG400EUXEN
DV90CGC0A0AEET	NV7B5740TBS/U5	DW60CG880B00ET	LC27G55TQBUXEN
DV90CGC0A0TEET	NV7B5755SBS/U5	DW60A8070BB/ET	LS32A700NWPXEN
DV90BB9445GMS3	NV7B4240UBB/U5	DW60A8060IB/ET	LS32C390EAUXEN
DV90T5240TW/S3	NV7B4340UBB/U5	DW60BG850B00ET	LS27C390EAUXEN
DV90T5240AW/S3	NV7B6679CBN/U5	DW50R4050BB/EO	LS32CM500EUXEN
DV90T7240BH/S3	NV7B41403BS/U5	NZ84T9747VK/UR	LS27CM501EUXEN
DV90T5240AE/S3	NV68A1110BS/ET	NZ64B5066FK/UI	LC27R500FHPXEN
DV90T5240AT/S3	NQ5B4513GBS/U5	NZ84T9747UK/UR	
DV90BB5245AWS3	NQ50T9539BD/ET	NZ84F7NB6AB/ET	
DV90CGC2A0TEET	NQ5B6753CAE/U5	NZ64B7799KK/UI	
DV90CGC2A0THET	NQ5B6753CAN/U5	NZ64B6058KK/UI	
DV80T7220BT/S3	NQ5B5713GBS/U5	NZ84F7NC6AB/ET	
DV80CGC0B0TEET	NQ5B4363EBS/U5	NZ64B5046GK/UI	
VS28C9784QK/WA	NV7B5640TBK/U5	NZ64B4016KK/UI	
VS20B95973B/WA	NQ50T9939BD/ET	NZ64T3707AK/ET	
VS20A95973B/WA	NQ50T8939BK/ET	NZ64B5066KK/UI	
VS20B95823W/WA	NQ5B7993AAN/U5	NZ64B5045GK/UI	
VS20C955CTK/WA	NQ50T8539BK/ET	NA64H3010AK/TI	
VS20C852FTB/WA	MG22M8274CT/EI	LS57CG952NUXEN	
VS20B75ACR5/WA	MG20A7013CT/ET	LS49CG934SUXEN	
VS15A60AGR5/WA	NQ5B5713GBK/U5	LS27C902PAUXEN	
VS15A6032R5/ET	MG23A7318CK/EI	LS49C950UAUXEN	
VS15A6031R1/ET	MS23A7318AK/EI	LS34BG850SUXEN	
VS15A6031R4/ET	MG22M8254AK/EI	LS32BG850NPXEN	
NV75T9979CD/ET	MS22M8274AM/EI	LS49CG950EUXEN	
NV7B4540VBK/U5	DW60M5070IB/ET	LS28BG700EPXEN	
NV7B4240UBS/U5	DW60BG850I00ET	LS32BG650EUXEN	